





MATERIAL SHOULD REST ON TOP OF THE JAW / FIXTURE AND ON THE 45° FACE.




When a proper dovetail is used, jaw/dovetail fixture acts as a wedge corner.

fracturing.



112.5mm (75%)


Dovetail width should not be less than 75% of the width of the stock.




SUPPORTING MATERIAL

Dovetail width should be narrow enough to support the part after material is removed.

THERE IS NO SIMPLE ANSWER TO HOW MUCH SUPPORT IS NEEDED.



If more support is needed, decrease dovetail width or increase tab thickness.




For narrow parts, position the dovetail as close as possible to the finished part's center of mass.






Clamping with a dovetail should **never** cause the material to locate on the bottom step of the jaw.




Locating on bottom step causes material to become a wedge trying to split the jaw.

This can break the jaw!




2. FINISHED PART UNSUPPORTED



A thin tab and/or insufficient material on the top locating surface will allow the part to move during machining.

2

3. OVERSIZED CORNER RADIUS




An overly wide inside corner radius allows material to contact the corner of the jaw, preventing it from locating correctly.

This will create excessive vibration during machining.




4. EXCESSIVELY WIDE DOVETAIL



Even though this part has tabs thick enough to prevent breaking, the dovetail is not positioned correctly under the part. This may result in excessive vertical vibration.

5. EXCESSIVELY NARROW DOVETAIL



Excessively narrow dovetail will concentrate support at the center of the stock and potentially cause chatter.

Keep in mind how and where force is applied to stock during machining.





DOVETAIL TROUBLESHOOTING GUIDE



The information in this document is applicable to **ALL** 5th AxisTM products with a dovetail feature.

4 5